

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	115	(strode or alarm) and (peak near current) with reduc\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 19:18
L2	332	(current near sensor) and current near regulator and comparat\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 18:37
L3	0	l1 and l2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 18:36
L4	0	l1 and current near regulator and comparat\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 18:37
L5	73	l1 and (current near sens\$3 or sens\$3 or resist\$2) and (switch\$3) and compar\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 18:38
L6	70	l5 and @ad<="20031117"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 19:18
L7	70	l6 and alarm	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 18:56
L8	94	(strode or alarm) same peak near current	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 18:57
L9	68	l8 and @ad<="20031117"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 18:57

L10	0	(strode) and (peak near current) with reduc\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 19:18
L11	115	alarm and (peak near current) with reduc\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 19:18
L12	110	l11 and @ad<="20031117"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 19:54
L13	77	l12 and compar\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 19:21
L14	55	l13 and port	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 19:37
L15	133	visual near output near devices	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 19:38
L16	0	control\$4 and (mechanically near movable or electrically near settable) and limit near3 peak near current near draw and switch\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 19:39
L17	0	control\$4 and (mechanically near movable or electrically near settable) and peak near current near draw and switch\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 19:39
L18	0	control\$4 and (mechanically near movable or electrically near settable) and peak near current near draw	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 19:40
L19	1822	control\$4 and (mechanically near movable or electrically near settable)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 19:40

L20	0	l15 and l19	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 19:40
L21	6	control\$4 and (mechanically near movable or electrically near settable) and peak near current	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 19:51
L22	0	control\$4 same current near limit\$4 and illumination near parameter and (visual near output or flashable near gas near fill\$2)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 19:54
L23	33	control\$4 same current near limit\$4 and parameter and (visual near output or flashable near gas near fill\$2)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 19:54
L24	30	l23 and @ad<="20031117"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/05/08 19:55